Work Orde Wednesday, July											Page 1
Revision ID:	D4035-041	alu Fund (250 Daglest)		Accept				i s	Setup Sta	1 19811181 8	
Item Name: Start Date: Required Date: Reference:	7/14/2010	Start Qty: 2.00 Req'd Qty: 2.00	1884 141 481 1844 161 161		Cust Item IJ Customer:	D:				*	1818 118 1181 1881
Approvals:	Process Plan	::_ <i> </i>	Date: 10-7-/9	Tooling: _ SPC (Y/N):		te:		I	Run Sta Sto		8148 114 1181 1181 1148 114 1181 1181
Sequence ID/ Work Center II		Operation Description		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr D4035	Revis A	sion Nbr							***·• ! •		· · · · · · · · · · · · · · · · · · ·
100 Large Fab Large Fab		Weld per dwg A/R S.S. Memo	rod Batch: 10521	0.00				9	(p	(10.0)G·EC
		2- Drill as pe 3- remove id	r dwg D4035 using DT95 entification marks and de ling in rib as per dwg D40	burr SA	0 10-07	-13					

110

QC9- Inspect visual per QSI004- Fusion Welds

0.00

QC

Memo

0.00

D 10.07.21

Quality Control

W/O:			V	VORK ORDER CHANG	iES					<u> </u>
DATE	STEP	PROC	EDURE CH	HANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							į			`*
				ALL COLORS						
									. '	
Part No	:	PAR #:	_ Fault Ca	itegory:	_ NCR	: Yes N	lo D Q	A:	_ Date: _	
	R	esolution:	_ Disposit	tion:	QA:	N/C Clo	sed:		Date: _	
NCR:		W	ORK OR	DER NON-CONFORM	ANCE	(NCR)				1.4.
DATE	STEP	Description of NC Section A	Initial	Action Description	tion B	Sign &		cation ion C	Approval Chief Eng	Approval QC Inspector
	 		Chief Eng	Chief Eng		Date				
									;	

Work Order ID 6054	Nork	. Or	der	H)	-60	540
--------------------	------	------	-----	----	-----	-----

Wednesday, July 14, 2010 8:19:42 AM



Page 2

Item ID:

D4035-041

Accept

Setup Start

Revision ID:

Item Name:

Lid Rib Assembly, Fwd (350 Basket)

Start Date:

7/14/2010

Start Oty: 2.00

Required Date: 7/22/2010 Req'd Qty: 2.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Date: _____

Tooling:

SPC (Y/N):

Date: Date:

Run

Start

Stop

Stop



Sequence ID/

Work Center ID

120

Quality Control

Operation Description

QC:

QC5- Inspect part completeness to step on W/O

Set Up/ **Run Hours**

0.00 8 10(0x151

Tool ID

Tool # Plan Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

130



Packaging

Memo

Memo

Identify as per dwg & Stock Location: (1)

0.00

0.00

SAD

10-07-21

140



Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10 107/21 H

W/O:			W	ORK ORDER CHANG	ES		`			
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									ļ	
			73.00.00							
Part No);	PAR #:	Fault Cat	egory:	_ NCR: Ye	s No D	QA:	Date: _	11.512.	
		esolution:								
NCR:		,	WORK ORI	DER NON-CONFORM	ANCE (N	CR)				
DATE	STEP	Description of NC			ion B	Ver	ification	Approval	Approval	
DAIE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sig Da		ection C	Chief Eng	QC Inspector	
						į				
1									-	
i.										
			•							

•													
Picklist Print													Page 1
Wednesday, July 14,	2010 8:19:46 AM												
Work Order ID: 605	46								1			-	
Parent Item: D40	035-041								ì				-
Parent Item Name:	Lid Rib Assembly, F	Fwd (350 Basket)	1100			-(1.50)		St	tart Date: 7/14	/2010	Require	d Date: 7/2	22/2010
								S	Start Qty: 2.00		Require	ed Qty: 2.0	00
	IPP RevA: new issu per dwg revA 10.03			l by:EC	IPP Rev	v:B as							
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2327-3 Spacer Bushing		Manufactured	No			100	Each	16.0000	1 T	2	p()	0.0	7.21
				Locatio	<u>n</u>	Loc	<u>Oty</u>	Loc Code		-			
				WA			16				_		
					58406 58974		1		_		_		
				>	59980		14		— کـ ،	Q	- -		
M304TS0.750W.049	1 2012 13 0 111 1 020 1 0 1111 20 12 2 0112 11	Purchased	No			100	f	234.2118		3.68421	1		
304 SQ Tube .75x.75x.04	 									SA)	10-0	7.13

114992

Location Loc Code Loc Qty MAT 44.73396794 113763 0 114323 23.9557189 114677 14.34201 114835 6.436239 MAT017 3.68448E-05 114298 3.6845E-05 WA 189.4778 3.6842 189.4778

W/O:			WC	RK ORDER CHANG	GES		·····			
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:	• *						Date:	
	Re	esolution:	Disposition	n:	QA:	N/C Cld	osed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORM	IANCE	(NCR)			
DATE	STEP	Description of NC Section A	Initial	Action Description	ction B	Sign &		cation ion C	Approval Chief Eng	Approval QC Inspector
			Chief Eng	Chief Eng		Date				

- ENGINEERING


SUNCONTROLLED GOPY

ITEM	QTY -041	QTY -043	QTY -045	QTY -047	P/N	DESCRIPTION	
	Х				D4035-041	LID RIB ASSY, FWD	
		X			D4035-043	LID RIB ASSY, AFT	
			X		D4035-045	LID RIB ASSY, FWD (LIGHT)	
				X	D4035-047	LID RIB ASSY, AFT (LIGHT)	
1	1				D4035-1	RIB	\dashv
2		1			D4035-3	RiB	\neg
3			1		D4035-5	RiB	\neg
4				1	D4035-7	RIB	_
5				2	D4035-11	BUSHING	
6	1		 	 	D2327-3	SPACER BUSHING	\dashv
7			1		D2953-175	SPACER	


D2953-175 D4021-9

BUSHING


SUBJECT TO AMENDMENT WITHOUT NOTICE WORK ORDER




D4035-041 BASKET LID RIB ASSY, FWD



D4035-043 BASKET LID RIB ASSY, AFT



D4035-045 BASKET LID RIB ASSY, FWD (LIGHT)




D4035-047 BASKET LID RIB ASSY, AFT (LIGHT)




A	NEW IS	SUE		JPH ;	10.03.04					
REV.		4	DESCRIPTION	BY	DATE					
DESIG	1	AJS	DART AEROSE	ACEL	TD.					
DRAW	1	JPJH		HAWKESBURY, ONTARIO, CANADA						
CHECKED			DRAWING NO.							
MFG. APPR.		A	D4035		SHEET 1 OF					
APPRO	VED	W	TITLE		SCALE					
DE APPR.		-44	BASKET LID RIB AS	SSY "	, NTS					
DATE	10.0	3.04	COPYRIGHT © 2010 BY DART AEROSPACE LTD THE GOOLMEN IS PRINATE, AND CONTIGHT IN A SUPPLET ON THE EXPRESE CONTIGHT THAT IT IS NOT TO BE USED FOR AMP PLAGOOGS OF CONCERNO ACTION TO MY OTHER PRISON WITHOUT							

Dart	Aerospace Ltd	
------	----------------------	--


W/O:			V	ORK ORDER CHANG	ES					
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Da	ate	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						-			Prod Wgr	,
•										
					,				•	
 										
Part No	:	PAR #:	Fault Ca	tegory:	_ NCR: Ye	es No	DQA	<u> </u>	Date:	
	R	esolution:	Disposit	ion:	_ QA: N/C	Close	d:		Date:	***************************************
NCR:		V	VORK OR	DER NON-CONFORMA	NCE (N	CR)				
DATE	STEP	Description of NC		Corrective Action Section		,	/erific	ation	Approval	Approval
	JILF	Section A	Initial Chief Eng	Action Description Chief Eng		n & ate	Section	n C	Chief Eng	QC Inspector
		,								
								·		
- r										
								•		<u>.</u>
l										
						1	ŀ			




W/O:			WC	ORK ORDER CHANGI	ES					
DATE	STEP	PRO	OCEDURE CHA	NGE	By	/	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						·				
Part No	:	PAR #:	Fault Cate	gory:	NCR: Y	es N	o DQA		_ Date: _	
	Re	esolution:	Dispositio	n:	_ QA: N/0	Clos	sed:		Date:	
NCR:			WORK ORD	ER NON-CONFORMA	NCE (N	CR)				
DATE	STEP	Description of NC Section A	Initial	Corrective Action Section Action Description	Si	gn &	Verifica Section		Approval Chief Eng	Approvai QC Inspector
			Chief Eng	Chief Eng		ate				
7-7										
	1		1 1		1		1 1		i	t



W/O:			V	VORK ORDER CHANG	GES				
DATE	STEP	PRO	OCEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						:			
						'			
Part No	:	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQ		Date:	
	R	esolution:	Disposit	ion:	QA: N/C (Closed:		Date: _	
NCR:			WORK OR	DER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC	Initial		etion B	Verific		Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	Dat	1 050110	h C	Chief Eng	QC Inspector
; 				·					



W/O:			WC	ORK ORDER CHANG	GES		,				
DATE	STEP	PROCEDURE CHANGE				Зу	Date	City	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
							1				
Part No:		PAR #:	Fault Category: NC			ICR: Yes No DQA:			Date:		
		solution:									
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCR))		,		
DATE	CTED	Description of NC Section A	Corrective Action Section B			Verifica		tion	Approval	Approval	
	STEP		Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	С	Chief Eng	QC Inspector	
				3-75-76-76-7-1							
•											



W/O:		WORK ORDER CHANGES								
DATE STEP		PROCEDURE CHANGE				Ву	Date	dty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								1	Prod Mgr	
									:	
								 		
	<u> </u>							-		
Part No:		PAR #:	Fault Category:			R: Yes N	lo DQA:	1		
	R	esolution:	tion: Disposition:				sed:			
NCR:		V	VORK OR	DER NON-CONFORM	ANCE	(NCR)	1			
DATE	STEP	Description of NC	Corrective Action Secti		1 VARITIA		Verifica	ation	Approval	Approval
DATE	SILP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector
	i									
	<u> </u>									·
			:							
							1			
*	-									
						•				
					.					